

Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects
IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report

Observation Dates:	03/03/14 thru 03/08/14
IEM Name:	Eric Sorenson
Waterbody Identification Number(s):	S-494-B, S-483-B,
Wetland Identification Number(s):	W-486-B, W-489-A, W-501-B
Enbridge Land Tract Identification Number(s):	N-618-1, N-619-8, N-626-6, N-648-2, N-623-1A, N-633-7, N-617-1
County(s): St.Joseph, LaPorte, Porter	Porter and LaPorte
<p>03/03/14: Crews continue with anomaly dig near Meridian Road. The crew will be making repairs to the silt fence upon completion of the dig. A crew has made some repairs to the wetland ECD'S W-485-Y N-619-10. Also repairs have been made to ECD'S at wetland W-493-Z N-626-7A. 03/04/14: Maintenance is being performed as needed throughout the ROW. Most locations still have a lot of snow drifts. 03/05/14: The contractor has completed repairs to the ECD'S at this wetland area. DNR streams throughout the ROW ECD'S are being maintained well. No environmental concerns. 03/06/14: The contractor continues with an anomaly dig near Meridian Road. Silt fence and other ECD'S that have been disturbed at the wetland boundary will be repaired. 03/07/14: Performed storm water inspections. 03/08/14: The contractor continues doing repairs as needed throughout the ROW.</p>	



sta#1075+00_MP485.6_W-485-Y_repairs made to ECD'S_W



segment1A_sta#1141+00_MP486.7_anamoly dig_W



sta#1505+00_MP493.6_ECD'S in working order_W12



sta#1272+00_MP489.2_W-489-A_ECD'S in working order_E



sta#1260+00_MP489.0_ECD'S repaired_W



sta#1563+00_MP494.6_S-494-B_DNR stream ECD'S in working order_N



sta#1912+00_MP501.2_W-501-B_ECD'S in working order_NE

